ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: M04406 Alaskan Copper Works Client: Date Received: PO M04406, F&BI 907320 07/30/09 Project: Lab ID: 907320-01 10x Date Extracted: 08/05/09 08/05/09 Data File: 907320-01 10x.029 Date Analyzed: Water Matrix: Instrument: ICPMS1

Matrix: Water Instrument: ICPMS
Units: ug/L (ppb) Operator: btb

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 104 60 125

286

53.6

Concentration ug/L (ppb)

Chromium 239
Nickel 206

Copper

Zinc

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank
Date Received: Not Applicable
Date Extracted: 08/05/09
Date Analyzed: 08/05/09
Matrix: Water
Units: ug/L (ppb)

Client: Alaskan Copper Works
Project: PO M04406, F&BI 907320
Lab ID: I9-319 mb
Data File: I9-319 mb.031
Instrument: ICPMS1
Operator: btb

Operator: b

Internal Standard: % Recovery: Germanium 108

Lower Upper Limit: Limit: 60 125

Concentration
Analyte: ug/L (ppb)

Chromium <1
Nickel <1
Copper <1
Zinc <1

ENVIRONMENTAL CHEMISTS

Date of Report: 08/12/09 Date Received: 07/30/09

Project: Metro Self Monitor, PO M04406, F&BI 907320

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 907327-08 (Duplicate)

Analyte	Reporting Units	Sample Result	Duplicate Result	Relative Percent Difference	Acceptance Criteria		
Chromium	ug/L (ppb)	<1	<1	nm	0-20		
Nickel	ug/L (ppb)	7.86	8.31	6	0-20		
Copper	ug/L (ppb)	<1	<1	nm	0-20		
Zinc	ug/L (ppb)	24.8	23.2	7	0-20		

Laboratory Code: 907327-08 (Matrix Spike)

Analyte	Reporting Units	Spike Level	Sample Result	Percent Recovery MS	Acceptance Criteria			
Chromium	ug/L (ppb)	20	<1	87	50-150			
Nickel	ug/L (ppb)	20	7.86	87 b	50-150			
Copper	ug/L (ppb)	20	<1	82	50-150			
Zinc	ug/L (ppb)	50	24.8	83 b	50-150			

Laboratory Code: Laboratory Control Sample

Analyte	Reporting Units	Spike Level	Percent Recovery LCS	Acceptance Criteria				
Chromium	ug/L (ppb)	20	99	70-130				
Nickel	ug/L (ppb)	20	94	70-130				
Copper	ug/L (ppb)	20	98	70-130				
Zinc	ug/L (ppb)	50	97	70-130				

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb The analyte indicated was found in the method blank. The result should be considered an estimate.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht The sample was extracted outside of holding time. Results should be considered estimates.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- ${\bf J}$ The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc -The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve The value reported exceeded the calibration range established for the analyte. The reported concentration should be considered an estimate.
- vo The value reported fell outside the control limits established for this analyte.
- x The pattern of peaks present is not indicative of diesel.
- y The pattern of peaks present is not indicative of motor oil.

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

August 12, 2009



INVOICE #09ACU0812-1

Accounts Payable Alaskan Copper Works 628 South Hanford Seattle, WA 98134

RE: Project Metro Self Monitor, PO M04406, F&BI 907320 - Results of testing requested by Gerry Thompson for material submitted on July 30, 2009.

FEDERAL TAX ID #(b) (6)

Send Penart To Select The Table					SAMPLERS (rignature)								TURNAROUND TIME					
Send Report To Septem 1 100 pour Company AUASKAN Coppen Works Address 628 S. HArring St			PROJECT NAMENO. Metro Self Moder REMARKS						MO	0# V40G		TURNAROUND TIME Standard (2. Weeks) RUSH 4 Czy Rush charges authorized by: SAMPLE DISPOSAL						
City, State, ZIP SeAT Phone # 206-571-60	2 F2F 74, -25	200 A			. 30 - 4	i i		.p2			27	11	🗆 Retu	ose after n sampl	30 days	. 9		
									AN	ALYS	SES REC	QUES'	ΓED	,				
Sample ID	Lab ID	Date	Time	Sample Typ	# of containers	TPH-Diesel	TPH-Gasoline	BTEX by 8021B	SVOCs by 8270	HFS	Ch Cu NE EN				No	otes		
m 09906	0[7/34/09	12:45	the	1				Į.		7							
								$\frac{1}{1}$										
				-		\dashv	+	+				-						
			·					1							·			
	9		*	-			1	_				-						
No. 10 Company of the	-	=		+:	42		+	+	-		\dashv	\dagger		+	on 12 - 10 -			
1. L		SYCON A STEET			MAN VA		1								Mari	TD:		
iedman & Bruya, Inc. 112 16th Avenue West	Retinquished to	SIGNATU	PRINT NAME Spark Thorse								Y00 3	TIM P. ZOS						
eattle, WA 98119-2029 h. (206) 285-8282	Retained by: Refinquished by:	af lan	$-\mid N$	Nhan Phan					}	e B			177	3919				
x (206) 283-5044	Received by:							-	\dashv					+				

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

August 12, 2009

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on July 30, 2009 from the Metro Self Monitor, PO M04406, F&BI 907320 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0812R.DOC